


General Information

Date & Time: 19, Oct, 2024 10:58

Make	Toyota	Model	Vios
YOM	2024	Mileage	8,895
Registration No.	NKA7966	Chassis No.	PA1B18F38P4236652
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Red		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	121.6	124	122	119
2	Boot Lid	118.0	118	117	119
3	Roof	117.7	126	122	105/118
4	Left Front Fender	105.3	108	103	105
5	Left Front Door	103.6	105	100	106
6	Center Panel Left				
7	Left Rear Door	115.0	120	113	112
8	Left Back Panel	123.6	125	120	126
9	Right Front Fender	119.0	106	126	125
10	Right Front Door	109.6	115	109	105
11	Center Panel Right				
12	Right Rear Door	132.6	114	146	138
13	Right Back Panel	114.6	121	114	109

Overall Evaluation :

A

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

Interior Evaluation : A		Exterior Evaluation : C	
			
a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain		A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap	
Remarks Defects not found		Remarks (L) Front Fender, Molding - Dent - Medium / Member (Bolted) - Dent - Yes / Front Bumper, Grille, Lamps - Scratch - Medium / (R) Rear Door, Molding - Scratch & Dent - Medium / (R) Rear Fender, Molding - Scratch & Dent - Medium / Trunk Hood, Rear Gate - Scratch - Small / Roof - Dent - Minimal / (L) Rear Door, Molding - Scratch - Minimal / (L) Front Door, Molding - Scratch - Small	
Frame Evaluation : A		Functional Evaluation : A	
Remarks Defects not found		Remarks Defects not found	

Inspector Notes

hairline scratches present/ dirty driver floor mat