

General Information

Date & Time: 26, May, 2025 10:08

Make	Toyota	Model	Raize
YOM	2024	Mileage	18,199
Registration No.	NKE3670	Chassis No.	MHKAB1BA8RJ090344
CC	1.2	Transmission	CVT
Fuel Type	Gas	Type of Body	SUV
Colour	Silver		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	108.5	95	124	107
2	Boot Lid	86.7	93	79	88
3	Roof	98.5	98	112	96/88
4	Left Front Fender	89.8	85	99	86
5	Left Front Door	97.8	98	96	100
6	Center Panel Left				
7	Left Rear Door	95.3	100	97	89
8	Left Back Panel	86.7	86	83	91
9	Right Front Fender	82.0	82	86	78
10	Right Front Door	86.5	85	93	82
11	Center Panel Right				
12	Right Rear Door	86.8	89	85	87
13	Right Back Panel	78.9	74	85	78

Overall Evaluation :

B

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : B	Exterior Evaluation : D
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
Remarks (R) Front Seat - Grime - Medium / (L) Front Seat - Grime - Medium / Rear Seat - Grime - Small / Dashboard - Traces of Adhesive Tape - Yes	Remarks (L) Front Fender, Molding - Partially Missing - Yes / (R) Front Fender, Molding - Scratch - Small / (R) Front Door, Molding - Scratch - Minimal / (R) Rear Door, Molding - Scratch & Dent - Medium / (R) Rear Fender, Molding - Scratch - Small / Rear Bumper, Lamps, Panels - Scratch - Small / Trunk Hood, Rear Gate - Scratch - Minimal / (L) Rear Fender, Molding - Scratch - Minimal / (L) Rear Door, Molding - Scratch - Medium / (L) Mirror - Scratch - Medium / (L) Front Door, Molding - Scratch - Minimal / (L) Front Fender, Molding - Scratch & Dent - Small / Front Bumper, Grille, Lamps - Crack, Gap - Medium
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Reverse Camera - N/A - Yes

Inspector Notes
with warranty booklet, with jack and tools, with spare tire, with LTO plate, left front fender partially missing