

General Information

Date & Time: 02, Jun, 2025 15:34

Make	Toyota	Model	Vios
YOM	2024	Odo Meter Reading	25,085
Registration No.	NKC8461	Chassis No.	PA1B18F39R4254547
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Red Mica Metallic		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	119.0	122	110	125
2	Boot Lid	113.6	105	107	129
3	Roof	101.3	110	102	94/100
4	Left Front Fender	96.3	97	91	101
5	Left Front Door	103.2	98	109	103
6	Center Panel Left				
7	Left Rear Door	103.8	108	104	100
8	Left Back Panel	109.3	120	107	101
9	Right Front Fender	102.5	108	100	100
10	Right Front Door	101.7	98	101	106
11	Center Panel Right				
12	Right Rear Door	106.3	102	107	110
13	Right Back Panel	106.0	106	98	114

Overall Evaluation :

C

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : C	Exterior Evaluation : E
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks Trunk Room - Worn, Scratch, Cut, Crack - Minimal / Rear Seat - Grime - Small / (R) Front Floor Mat - Grime - Medium / (L) Front Floor Mat - Worked - Large / Ceiling - Grime - Small</p>	<p>Remarks (R) Front Fender, Molding - Dent - Medium / (R) Mirror - Scratch - Minimal / (R) Front Door, Molding - Scratch - Small / (R) Rear Door, Molding - Scratch - Small / (R) Rear Fender, Molding - Scratch - Minimal / Rear Bumper, Lamps, Panels - Scratch - Large / Trunk Hood, Rear Gate - Scratch - Medium / Roof - Scratch - Small / (L) Rear Fender, Molding - Scratch & Dent - Minimal / (L) Rear Door, Molding - Scratch - Medium / (L) Front Door, Molding - Scratch - Large / (L) Mirror - Scratch - Small / (L) Front Fender, Molding - Scratch - Small / Front Bumper, Grille, Lamps - Scratch & Dent - Medium / Bonnet, Headlight - Scratch - Minimal</p>
Frame Evaluation : A	Functional Evaluation : A
<p>Remarks Defects not found</p>	<p>Remarks Spare Key - Issue - Unexist</p>

<p>Inspector Notes</p>
<p>With LTO plate, no warranty booklet, with jack, no tools, with spare tire, damaged reverse sensor</p>