

General Information

Date & Time: 19, Oct, 2024 13:04

Make	Toyota	Model	Vios
YOM	2024	Mileage	11,870
Registration No.	EAG9051	Chassis No.	PA1B18F34R4245898
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Black		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	128.3	137	118	130
2	Boot Lid	116.6	113	120	117
3	Roof	118.7	120	115	113/127
4	Left Front Fender	117.3	130	115	107
5	Left Front Door	107.3	104	104	114
6	Center Panel Left				
7	Left Rear Door	118.0	125	117	112
8	Left Back Panel	126.0	133	129	116
9	Right Front Fender	112.6	111	111	116
10	Right Front Door	113.3	121	106	113
11	Center Panel Right				
12	Right Rear Door	118.6	111	112	133
13	Right Back Panel	124.6	119	118	137

Overall Evaluation :

A

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

Interior Evaluation : A	Exterior Evaluation : B
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Dashboard - Traces of Adhesive Tape - Yes	Remarks Front Bumper, Grille, Lamps - Scratch - Medium / (R) Rear Door, Molding - Scratch - Small / (R) Rear Fender, Molding - Scratch - Small / Trunk Hood, Rear Gate - Scratch - Small / (R) Front Fender, Molding - Scratch - Minimal
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Defects not found

Inspector Notes

a lot of hairline scratches and swirl marks/ adhesive scratch on the hood.