

General Information

Date & Time: 03, Jun, 2025 15:04

Make	Toyota	Model	Vios
YOM	2024	Odo Meter Reading	27,235
Registration No.	NHM4104	Chassis No.	PA1B18F30P4231400
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Black		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	117.0	117	111	123
2	Boot Lid	108.6	105	104	117
3	Roof	114.5	111	115	115/117
4	Left Front Fender	106.0	110	104	104
5	Left Front Door	101.2	101	104	99
6	Center Panel Left				
7	Left Rear Door	111.6	108	127	100
8	Left Back Panel	121.3	129	115	120
9	Right Front Fender	100.5	98	101	103
10	Right Front Door	108.3	111	103	111
11	Center Panel Right				
12	Right Rear Door	114.6	110	113	121
13	Right Back Panel	123.0	114	120	135

Overall Evaluation :

A

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : B	Exterior Evaluation : A
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks (R) Front Floor Mat - Missing - Yes / (L) Front Floor Mat - Missing - Yes / Mat Other - Missing - Yes</p>	<p>Remarks Bonnet, Headlight - Scratch - Small / Rear Bumper, Lamps, Panels - Scratch - Small / (R) Rear Door, Molding - Scratch - Small / (L) Front Door, Molding - Scratch - Minimal / (L) Rear Door, Molding - Scratch - Minimal / Roof - Scratch - Minimal</p>
Frame Evaluation : A	Functional Evaluation : B
<p>Remarks Defects not found</p>	<p>Remarks Battery - Weak - Yes / Reverse Camera - N/A - Yes / Wiper - Function - Weak</p>

<p>Inspector Notes</p>
<p>with warranty booklet and LTO plate, Jack and sparetire. no Tools.</p>