

General Information

Date & Time: 30, May, 2025 14:44

Make	Toyota	Model	Innova
YOM	2023	Odo Meter Reading	65,428
Registration No.	NHI8907	Chassis No.	PA2JA8EMXP0123682
CC	2.8	Transmission	A/T
Fuel Type	Diesel	Type of Body	Wagon
Colour	Silver		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	104.2	96	127	90
2	Boot Lid	99.2	101	98	98
3	Roof	104.1	103	98	114/102
4	Left Front Fender	95.3	87	100	100
5	Left Front Door	103.1	100	112	97
6	Center Panel Left				
7	Left Rear Door	104.6	108	103	103
8	Left Back Panel	118.0	110	113	131
9	Right Front Fender	92.1	87	102	87
10	Right Front Door	104.0	102	107	103
11	Center Panel Right				
12	Right Rear Door	99.0	92	100	105
13	Right Back Panel	106.6	107	108	105

Overall Evaluation :

B

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : C	Exterior Evaluation : C
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks (R) Rear Trim - Grime - Minimal / (R) Front Trim - Grime - Small / (L) Front Floor Mat - Worked - Small / (L) Front Trim - Grime - Small / Console, Switchs, Vents - Traces of Adhesive Tape - Yes / Ceiling - Grime - Large</p>	<p>Remarks Member (Bolted) - Dent - Yes / (R) Mirror - Scratch - Minimal / (R) Rear Fender, Molding - Scratch & Dent - Medium / Rear Bumper, Lamps, Panels - Scratch - Medium / (L) Rear Door, Molding - Scratch & Dent - Small / (L) Front Door, Molding - Scratch - Small / (L) Front Fender, Molding - Scratch - Medium / Front Bumper, Grille, Lamps - Crack, Gap - Medium / Bonnet, Headlight - Scratch - Minimal / Trunk Hood, Rear Gate - Scratch - Minimal</p>
Frame Evaluation : A	Functional Evaluation : A
<p>Remarks Defects not found</p>	<p>Remarks Reverse Camera - N/A - Yes / Lamps (Brake, Tail, Fog) - Issue - Yes / Spare Key - Issue - Unexist</p>

<p>Inspector Notes</p>
<p>no warranty booklet, with jack and tools, with spare tire, with LTO plate</p>