

General Information

Date & Time: 29, May, 2025 12:12

Make	Toyota	Model	Vios
YOM	2024	Odo Meter Reading	13,351
Registration No.	DBN9646-1	Chassis No.	PA1B18F37P4237761
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Green		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	103.0	106	98	105
2	Boot Lid	106.2	107	98	114
3	Roof	111.6	93	103	125/126
4	Left Front Fender	98.3	106	100	89
5	Left Front Door	97.0	111	92	89
6	Center Panel Left				
7	Left Rear Door	103.6	135	89	87
8	Left Back Panel	86.8	87	89	86
9	Right Front Fender	99.7	101	100	98
10	Right Front Door	79.2	90	83	66
11	Center Panel Right				
12	Right Rear Door	87.1	90	87	85
13	Right Back Panel	95.9	88	103	97

Overall Evaluation :

B

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : B	Exterior Evaluation : C
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
Remarks Overall Interior - Animal Hair - Yes / (R) Front Seat - Grime - Medium / (L) Front Floor Mat - Worked - Small	Remarks Front Bumper, Grille, Lamps - Scratch - Small / (R) Front Fender, Molding - Scratch & Dent - Medium / (R) Rear Door, Molding - Scratch - Medium / (R) Rear Fender, Molding - Scratch - Small / Trunk Hood, Rear Gate - Scratch - Minimal / (L) Front Door, Molding - Scratch - Large / Roof - Scratch - Minimal
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Defects not found

Inspector Notes
with LTO plate and warranty booklet, jack, spare tire, and tools.