

General Information

Date & Time: 19, Oct, 2024 09:14

Make	Toyota	Model	Vios
YOM	2024	Mileage	8,153
Registration No.	BAF9470	Chassis No.	PA1B18F33R4246198
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Red		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	129.6	136	125	128
2	Boot Lid	128.0	115	125	144
3	Roof	124.0	126	124	114/132
4	Left Front Fender	117.3	122	115	115
5	Left Front Door	119.6	117	120	122
6	Center Panel Left				
7	Left Rear Door	119.0	121	118	118
8	Left Back Panel	127.3	135	125	122
9	Right Front Fender	126.0	128	126	124
10	Right Front Door	120.6	120	117	125
11	Center Panel Right				
12	Right Rear Door	128.3	125	137	123
13	Right Back Panel	137.6	125	123	165

Overall Evaluation :

A

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

Interior Evaluation : A	Exterior Evaluation : B
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Defects not found	Remarks (L) Rear Door, Molding - Scratch & Dent - Medium / Roof - Scratch - Minimal / Bonnet, Headlight - Scratch - Minimal / Rear Bumper, Lamps, Panels - Scratch & Dent - Small / Trunk Hood, Rear Gate - Scratch & Dent - Small / Front Bumper, Grille, Lamps - Scratch - Medium
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Defects not found

Inspector Notes
hairline left side front door