

## General Information

Date & Time: 03, Jun, 2025 16:49

<b>Make</b>	Toyota	<b>Model</b>	Vios
<b>YOM</b>	2024	<b>Odo Meter Reading</b>	9,935
<b>Registration No.</b>	NHQ6164	<b>Chassis No.</b>	PA1B18F31R4251531
<b>CC</b>	1.3	<b>Transmission</b>	CVT
<b>Fuel Type</b>	Gas	<b>Type of Body</b>	Sedan
<b>Colour</b>	Blue		

## Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	<b>118.3</b>	124	119	112
2	Boot Lid	<b>109.0</b>	111	101	115
3	Roof	<b>103.4</b>	113	106	92/103
4	Left Front Fender	<b>105.6</b>	107	104	106
5	Left Front Door	<b>105.0</b>	100	110	105
6	Center Panel Left				
7	Left Rear Door	<b>103.3</b>	108	102	100
8	Left Back Panel	<b>114.0</b>	117	110	115
9	Right Front Fender	<b>103.7</b>	104	99	108
10	Right Front Door	<b>107.0</b>	103	106	112
11	Center Panel Right				
12	Right Rear Door	<b>103.6</b>	100	100	111
13	Right Back Panel	<b>104.0</b>	108	102	102

**Overall Evaluation :**

**B**

### Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

<b>Interior Evaluation :</b> <span style="float: right; color: red; font-weight: bold;">C</span>	<b>Exterior Evaluation :</b> <span style="float: right; color: red; font-weight: bold;">C</span>
 <p><b>a</b> : Cut, Fray <b>d</b> : Loose, Deformed <b>k</b> : Animal Hair <b>s</b> : Smell <b>t</b> : Cigarette Burns <b>x</b> : Defective <b>y</b> : Stain</p>	 <p><b>A</b> : Scratch <b>AU</b> : Scratch &amp; Dent <b>B</b> : Modified <b>C</b> : Corrosion <b>G</b> : Stone chip <b>P</b> : Faded <b>S</b> : Rust <b>SC</b> : Rust &amp; Corrosion <b>U</b> : Dent <b>X</b> : Defective <b>Y</b> : Crack, Gap</p>
<p><b>Remarks</b> Mat Other - Grime - Medium / Rear Seat - Grime - Medium / (R) Front Trim - Grime - Minimal / (R) Front Floor Mat - Grime - Medium / (L) Rear Trim - Grime - Minimal / (L) Front Floor Mat - Worked - Small / (L) Front Floor Mat - Grime - Medium</p>	<p><b>Remarks</b> (R) Front Fender, Molding - Dent - Small / (R) Mirror - Scratch - Minimal / (R) Rear Door, Molding - Scratch - Large / (R) Rear Fender, Molding - Scratch - Medium / (L) Rear Door, Molding - Scratch - Small / (L) Mirror - Scratch - Minimal / Bonnet, Headlight - Scratch - Minimal</p>
<b>Frame Evaluation :</b> <span style="float: right; color: red; font-weight: bold;">A</span>	<b>Functional Evaluation :</b> <span style="float: right; color: red; font-weight: bold;">A</span>
<p><b>Remarks</b> Defects not found</p>	<p><b>Remarks</b> Lamps (Brake, Tail, Fog) - Issue - Yes / Spare Key - Issue - Unexist</p>

<p><b>Inspector Notes</b></p>
<p>no warranty booklet, with jack, no tools, with spare tire, with LTO plate, dome light issue</p>