

General Information

Date & Time: 03, Jun, 2025 10:41

Make	Toyota	Model	Vios
YOM	2022	Odo Meter Reading	44,409
Registration No.	NFG3959	Chassis No.	PA1B8F38M4164430
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Red		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	107.6	104	108	111
2	Boot Lid	107.6	100	112	111
3	Roof	99.2	109	84	100/105
4	Left Front Fender	100.8	106	106	91
5	Left Front Door	96.8	98	97	96
6	Center Panel Left				
7	Left Rear Door	96.1	87	97	104
8	Left Back Panel	111.6	114	110	111
9	Right Front Fender	88.0	88	88	88
10	Right Front Door	96.3	95	98	97
11	Center Panel Right				
12	Right Rear Door	98.7	104	93	100
13	Right Back Panel	102.2	98	99	110

Overall Evaluation :

C

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : C	Exterior Evaluation : E
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks (R) Front Seat - Grime - Large / (L) Front Seat - Grime - Medium / Rear Seat - Grime - Medium / (R) Front Trim - Grime - Small / (L) Front Trim - Grime - Medium / (L) Front Floor Mat - Cut, Crack - Small / (L) Front Floor Mat - Worked - Small / (R) Front Floor Mat - Missing - Yes / Mat Other - Missing - Yes / Sunvisor, Sunglass Holder - Missing - Yes / Ceiling - Grime - Small</p>	<p>Remarks (R) Front Fender, Molding - Scratch - Small / (R) Mirror - Scratch - Minimal / (R) Front Door, Molding - Scratch - Medium / (R) Rear Door, Molding - Scratch - Small / Rear Bumper, Lamps, Panels - Scratch & Dent - Large / Trunk Hood, Rear Gate - Scratch & Dent - Large / (L) Rear Fender, Molding - Scratch - Medium / (L) Rear Door, Molding - Scratch - Medium / (L) Front Door, Molding - Scratch & Dent - Minimal / (L) Mirror - Scratch - Small / (L) Front Fender, Molding - Scratch - Small / Front Bumper, Grille, Lamps - Scratch - Large</p>
Frame Evaluation : A	Functional Evaluation : A
<p>Remarks Defects not found</p>	<p>Remarks Reverse Camera - N/A - Yes / Horn - Issue - Yes / Spare Key - Issue - Unexist</p>

<p>Inspector Notes</p>
<p>no warranty booklet, with jack, no tools, with spare tire, with LTO plate</p>