

General Information

Date & Time: 03, Jun, 2025 15:33

Make	Toyota	Model	Raize
YOM	2024	Odo Meter Reading	5,004
Registration No.	NFR7454	Chassis No.	MHKAB1BA2RJ081705
CC	1.2	Transmission	CVT
Fuel Type	Gas	Type of Body	SUV
Colour	Red		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	107.0	100	113	108
2	Boot Lid	96.1	87	124	77
3	Roof	98.9	95	113	95/93
4	Left Front Fender	89.6	89	92	88
5	Left Front Door	97.2	96	97	99
6	Center Panel Left				
7	Left Rear Door	95.7	97	98	92
8	Left Back Panel	89.5	86	87	96
9	Right Front Fender	83.8	79	90	83
10	Right Front Door	85.8	91	84	83
11	Center Panel Right				
12	Right Rear Door	89.9	88	86	96
13	Right Back Panel	87.6	88	95	81

Overall Evaluation :

A

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : A	Exterior Evaluation : A
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
Remarks (L) Front Floor Mat - Worked - Small	Remarks (R) Front Door, Molding - Scratch - Minimal / (R) Rear Fender, Molding - Scratch - Minimal / Bonnet, Headlight - Scratch - Minimal
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Defects not found

Inspector Notes
with warranty booklet, with jack and tools, with spare tire, with LTO plate