

General Information

Date & Time: 31, May, 2025 15:47

Make	Toyota	Model	Lite Ace
YOM	2023	Odo Meter Reading	22,298
Registration No.	BAF6329	Chassis No.	MHKB3FE10NK001415
CC	1.5	Transmission	M/T
Fuel Type	Gas	Type of Body	Van
Colour	White		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	62.9	62	69	58
2	Boot Lid	47.8	44	57	43
3	Roof	62.1	58	50	62/78
4	Left Front Fender	45.6	42	44	52
5	Left Front Door	48.5	48	48	49
6	Center Panel Left				
7	Left Rear Door	95.8	96	95	97
8	Left Back Panel	53.5	48	55	58
9	Right Front Fender	53.7	61	49	51
10	Right Front Door	45.9	43	48	46
11	Center Panel Right				
12	Right Rear Door	61.2	56	52	76
13	Right Back Panel	56.6	53	52	64

Overall Evaluation :

B

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : C	Exterior Evaluation : C
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks Ceiling - Grime - Large / Carpet - Worked - Large / Mat Other - Worked - Large / Overall Interior - Smell - Yes / (R) Front Floor Mat - Worked - Small / (L) Front Floor Mat - Worked - Small / Dashboard - Worked - Minimal / (R) Front Seat - Grime - Small / (L) Front Seat - Grime - Small</p>	<p>Remarks Trunk Hood, Rear Gate - Scratch & Dent - Small / (R) Rear Fender, Molding - Scratch - Small / (R) Rear Door, Molding - Scratch - Large / Rear Bumper, Lamps, Panels - Scratch - Small / (L) Front Door, Molding - Scratch - Small / (L) Step, In-panel, Side Spoiler - Scratch - Small / (L) Rear Door, Molding - Scratch - Small / Bonnet, Headlight - Scratch - Small / Front Bumper, Grille, Lamps - Scratch - Small / (R) Front Door, Molding - Scratch - Small / Roof Spoiler, Molding - Scratch & Dent - Small / (R) Front Fender, Molding - Scratch - Small</p>
Frame Evaluation : A	Functional Evaluation : A
<p>Remarks Defects not found</p>	<p>Remarks Reverse Camera - N/A - Yes</p>

<p>Inspector Notes</p>
<p>with warranty booklet and LTO plate, Jack, Sparetire and incomplete tools. scratch headlight.</p>