

General Information

Date & Time: 23, May, 2025 12:30

Make	Suzuki	Model	Ertiga
YOM	2020	Mileage	31,381
Registration No.	CAT2636	Chassis No.	MHYNC22S9LJ109669
CC	1.5	Transmission	A/T
Fuel Type	Gas	Type of Body	Wagon
Colour	White		

Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	86.7	88	84	89
2	Boot Lid	90.8	90	94	89
3	Roof	193.5	285	205	145/139
4	Left Front Fender	86.4	87	85	87
5	Left Front Door	101.7	107	96	102
6	Center Panel Left				
7	Left Rear Door	101.1	107	101	95
8	Left Back Panel	104.3	107	109	97
9	Right Front Fender	84.8	86	85	84
10	Right Front Door	221.3	183	209	272
11	Center Panel Right				
12	Right Rear Door	94.9	93	93	99
13	Right Back Panel	94.4	90	95	98

Overall Evaluation :

B

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : B	Exterior Evaluation : D
<p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	<p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks (R) Front Seat - Grime - Medium / (R) Front Floor Mat - Grime - Small / Mat Other - Missing - Yes / Ceiling - Grime - Medium / Rear Seat - Grime - Medium</p>	<p>Remarks (R) Front Door - Repair Traces - Yes / (R) Step - Repair Traces - Yes / Roof - Repair Traces - Yes / (R) Mirror - Scratch - Medium / Trunk Hood, Rear Gate - Scratch & Dent - Small / Front Bumper, Grille, Lamps - Scratch & Dent - Large / Bonnet, Headlight - Scratch - Small / (R) Front Fender, Molding - Scratch & Dent - Medium / (R) Step, In-panel, Side Spoiler - Scratch - Small / Rear Bumper, Lamps, Panels - Scratch & Dent - Medium / (R) Rear Fender, Molding - Scratch - Small / (L) Front Fender, Molding - Dent - Small / (L) Rear Door, Molding - Scratch & Dent - Large / Roof - Dent - Small</p>
Frame Evaluation : A	Functional Evaluation : A
<p>Remarks Defects not found</p>	<p>Remarks Reverse Camera - N/A - Yes / Spare Key - Issue - Unexist</p>

<p>Inspector Notes</p>
<p>without warranty booklet and seatcover. With spare tire, jack and tools. 1 key. With warranty booklet.</p>