

General Information

Date & Time: 23, May, 2025 10:58

Make	Hyundai	Model	Stargazer
YOM	2023	Mileage	61,755
Registration No.	NIN5817	Chassis No.	MF3NB81DEPJ009009
CC	1.5	Transmission	A/T
Fuel Type	Gas	Type of Body	MPV
Colour	Black		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	134.3	135	133	135
2	Boot Lid	91.2	92	91	91
3	Roof	103.4	108	106	100/100
4	Left Front Fender	104.4	90	115	108
5	Left Front Door	118.3	125	121	109
6	Center Panel Left				
7	Left Rear Door	120.3	126	120	115
8	Left Back Panel	113.0	112	111	116
9	Right Front Fender	104.8	113	102	99
10	Right Front Door	114.3	108	112	123
11	Center Panel Right				
12	Right Rear Door	121.0	117	117	129
13	Right Back Panel	110.0	118	106	106

Overall Evaluation :

B

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : A	Exterior Evaluation : D
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks Ceiling - Grime - Small / Sunvisor, Sunglass Holder - Crinkle - Small / (R) Rear Trim - Grime - Small</p>	<p>Remarks (L) Rear Door, Molding - Repair mark - Yes / (L) Rear Fender, Molding - Repair mark - Yes / (L) Rear Fender, Molding - Scratch - Large / (L) Rear Door, Molding - Scratch - Medium / (L) Front Door, Molding - Scratch - Small / (L) Mirror - Scratch - Small / (L) Front Fender, Molding - Scratch - Small / (R) Rear Fender, Molding - Scratch - Small / (R) Front Door, Molding - Scratch - Small / Rear Bumper, Lamps, Panels - Repair mark - Yes / Rear Bumper, Lamps, Panels - Scratch - Medium / Roof - Dent - Minimal / Front Bumper, Grille, Lamps - Dent - Small</p>
Frame Evaluation : A	Functional Evaluation : A
<p>Remarks Defects not found</p>	<p>Remarks Reverse Camera - N/A - Yes / Spare Key - Issue - Unexist</p>

<p>Inspector Notes</p>
<p>Without warranty booklet. With Spare tire, jack, tools and seat cover. 1 key. With LTO plate.</p>