

General Information

Date & Time: 19, Oct, 2024 11:13

Make	Toyota	Model	Vios
YOM	2024	Mileage	6,710
Registration No.	CCC8240	Chassis No.	PA1B18F32R4252011
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Black		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	123.3	124	118	128
2	Boot Lid	121.0	127	115	121
3	Roof	116.7	124	117	107/119
4	Left Front Fender	111.6	116	107	112
5	Left Front Door	116.3	123	113	113
6	Center Panel Left				
7	Left Rear Door	118.6	119	116	121
8	Left Back Panel	125.6	136	119	122
9	Right Front Fender	120.3	135	111	115
10	Right Front Door	118.6	118	116	122
11	Center Panel Right				
12	Right Rear Door	118.3	108	119	128
13	Right Back Panel	120.3	119	112	130

Overall Evaluation :

A

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

Interior Evaluation : A	Exterior Evaluation : A
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks (L) Front Floor Lag - Loose, Deformed, Grime - Small	Remarks Front Bumper, Grille, Lamps - Scratch & Dent - Small / Bonnet, Headlight - Scratch - Minimal / (R) Front Door, Molding - Scratch - Minimal / (R) Rear Door, Molding - Scratch - Minimal / (R) Rear Fender, Molding - Scratch - Minimal / Trunk Hood, Rear Gate - Scratch - Minimal / Roof - Scratch - Minimal
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Defects not found

Inspector Notes
hairline scratches and swirl marks