


General Information

Date & Time: 26, May, 2025 12:59

Make	Toyota	Model	Hiace
YOM	2025	Mileage	3
Registration No.	DA496B	Chassis No.	JTFNAFAP1S8055358
CC	2.8	Transmission	M/T
Fuel Type	Diesel	Type of Body	Van
Colour	White		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet				
2	Boot Lid				
3	Roof				
4	Left Front Fender				
5	Left Front Door				
6	Center Panel Left				
7	Left Rear Door				
8	Left Back Panel				
9	Right Front Fender				
10	Right Front Door				
11	Center Panel Right				
12	Right Rear Door				
13	Right Back Panel				

Overall Evaluation :

A

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : A	Exterior Evaluation : B
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Defects not found	Remarks Bonnet, Headlight - Dent - Medium / Roof - Dent - Medium
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Defects not found

Inspector Notes

cluster of dents on roof and hood.