

General Information

Date & Time: 04, Jun, 2025 11:26

Make	Toyota	Model	Avanza
YOM	2023	Odo Meter Reading	53,395
Registration No.	NHC5504	Chassis No.	MHFAA1BY2N0009207
CC	1.3	Transmission	M/T
Fuel Type	Gas	Type of Body	MPV
Colour	Silver		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	137.6	123	135	155
2	Boot Lid	118.6	124	132	100
3	Roof	127.2	132	128	117/132
4	Left Front Fender	103.7	98	102	111
5	Left Front Door	120.0	135	115	110
6	Center Panel Left				
7	Left Rear Door	124.0	127	119	126
8	Left Back Panel	115.6	122	118	107
9	Right Front Fender	109.6	117	105	107
10	Right Front Door	117.6	117	108	128
11	Center Panel Right				
12	Right Rear Door	125.0	132	114	129
13	Right Back Panel	152.6	133	163	162

Overall Evaluation :

C

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : C	Exterior Evaluation : C
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
Remarks Overall Interior - Worn as per age - Yes	Remarks Bonnet - Repair Traces - Yes / (L) Front Fender - Repair Traces - Yes / Front Bumper, Grille, Lamps - Repair mark - Yes / Bonnet, Headlight - Dent - Medium / Bonnet, Headlight - Repair mark - Yes / (R) Rear Door, Molding - Scratch & Dent - Medium / Front Bumper, Grille, Lamps - Scratch - Small / (L) Rear Fender, Molding - Scratch - Small / (R) Front Door, Molding - Scratch - Minimal / (L) Rear Door, Molding - Scratch - Minimal / Trunk Hood, Rear Gate - Scratch - Minimal / (L) Front Door, Molding - Scratch - Minimal / (L) Front Fender, Molding - Scratch - Minimal / (R) Front Fender, Molding - Scratch - Small / Rear Bumper, Lamps, Panels - Scratch - Minimal / (R) Rear Fender, Molding - Scratch - Minimal
Frame Evaluation : A	Functional Evaluation : B
Remarks Defects not found	Remarks Battery - Weak - Yes / Reverse Camera - N/A - Yes

Inspector Notes
With LTO plate and sparetire. No warranty booklet and tools, Jack. adhesive marks on hood and side mirror.