

General Information

Date & Time: 19, Oct, 2024 15:01

Make	Toyota	Model	Vios
YOM	2024	Mileage	13,117
Registration No.	BAF7876	Chassis No.	PA1B18F30P4238041
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Silver		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	121.3	127	120	117
2	Boot Lid	122.3	119	125	123
3	Roof	115.0	124	111	113/112
4	Left Front Fender	109.0	112	104	111
5	Left Front Door	110.0	110	109	111
6	Center Panel Left				
7	Left Rear Door	112.0	121	109	106
8	Left Back Panel	123.6	129	125	117
9	Right Front Fender	114.3	113	115	115
10	Right Front Door	115.3	117	113	116
11	Center Panel Right				
12	Right Rear Door	119.0	113	117	127
13	Right Back Panel	125.3	132	122	122

Overall Evaluation :

A

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

Interior Evaluation : A	Exterior Evaluation : A
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Trunk Room - Loose, Deformed, Grime - Small	Remarks Front Bumper, Grille, Lamps - Scratch - Small / Rear Bumper, Lamps, Panels - Scratch - Small
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Reverse Camera - N/A - Yes / Spare Key - Issue - Unexist

Inspector Notes
reverse camera not aligned/ hairline scratches and swirl marks present/ very good condition