

General Information

Date & Time: 04, Jun, 2025 13:30

Make	Toyota	Model	Avanza
YOM	2024	Odo Meter Reading	7,489
Registration No.	NHS2907	Chassis No.	MHFAA1BY8R0026289
CC	1.3	Transmission	M/T
Fuel Type	Gas	Type of Body	MPV
Colour	Black		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	115.0	112	113	120
2	Boot Lid	106.2	96	115	108
3	Roof	117.0	118	130	112/108
4	Left Front Fender	108.0	110	113	101
5	Left Front Door	122.6	114	128	126
6	Center Panel Left				
7	Left Rear Door	117.0	113	114	124
8	Left Back Panel	119.3	133	109	116
9	Right Front Fender	114.6	122	108	114
10	Right Front Door	120.6	128	121	113
11	Center Panel Right				
12	Right Rear Door	122.6	123	119	126
13	Right Back Panel	111.3	114	102	118

Overall Evaluation :

A

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : B	Exterior Evaluation : B
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
Remarks Rear Seat - Grime - Small / Ceiling - Grime - Minimal / (R) Front Seat - Grime - Medium	Remarks (R) Front Fender, Molding - Rust, Corrosion - Small / (R) Front Door, Molding - Scratch - Minimal / (R) Rear Door, Molding - Scratch - Minimal / (R) Rear Fender, Molding - Scratch - Minimal / Rear Bumper, Lamps, Panels - Scratch - Small / Trunk Hood, Rear Gate - Scratch - Minimal / (L) Rear Fender, Molding - Scratch - Minimal / (L) Rear Door, Molding - Scratch - Minimal / (L) Step, In-panel, Side Spoiler - Scratch - Small / (L) Front Fender, Molding - Scratch - Minimal / Roof - Scratch - Minimal / Front Bumper, Grille, Lamps - Scratch - Minimal / Bonnet, Headlight - Scratch - Minimal
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Reverse Camera - N/A - Yes / Spare Key - Issue - Unexist

Inspector Notes
with LTO plate, no warranty booklet, no jack and tools, with spare tire