


General Information

Date & Time: 29, May, 2025 17:28

Make	Toyota	Model	Hiace
YOM	2021	Odo Meter Reading	129,000
Registration No.	DAP1491	Chassis No.	JTFJT02P5M5027751
CC	3.0	Transmission	M/T
Fuel Type	Diesel	Type of Body	Van
Colour	White		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	69.6	71	69	69
2	Boot Lid	75.8	71	77	80
3	Roof	66.6	58	69	66/74
4	Left Front Fender	73.8	66	79	77
5	Left Front Door	61.9	70	55	62
6	Center Panel Left				
7	Left Rear Door				
8	Left Back Panel	66.6	66	64	70
9	Right Front Fender	76.7	77	77	76
10	Right Front Door	60.7	61	59	62
11	Center Panel Right				
12	Right Rear Door	69.4	71	68	70
13	Right Back Panel	71.4	74	71	69

Overall Evaluation :

C

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : C	Exterior Evaluation : D
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Sunvisor, Sunglass Holder - Grime - Medium / Ceiling - Grime - Large / Dashboard - Traces of Adhesive Tape - Yes / Rear Seat - Partially Missing - Yes	Remarks (R) Center Panel - Scratch - Small / (R) Mirror - Scratch - Small / Front Bumper, Grille, Lamps - Scratch & Dent - Large / Roof - Dent - Small / (R) Rear Door, Molding - Scratch & Dent - Large / (R) Rear Fender, Molding - Scratch - Small / Rear Bumper, Lamps, Panels - Scratch - Medium / (L) Rear Fender, Molding - Scratch - Small / (L) Mirror - Scratch - Small / (L) Front Fender, Molding - Scratch - Minimal / (L) Front Door, Molding - Scratch - Small / Bonnet, Headlight - Scratch - Minimal
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Reverse Camera - N/A - Yes / Spare Key - Issue - Unexist

Inspector Notes
Modified exhaust system. missing one seat. without warranty booklet and tools. With jack and spare tire. 1 key. with LTO plate