

General Information

Date & Time: 29, May, 2025 18:28

Make	Toyota	Model	Hiace
YOM	2024	Odo Meter Reading	28,946
Registration No.	NIT1233	Chassis No.	JTFJT02P5P0017903
CC	3.0	Transmission	M/T
Fuel Type	Diesel	Type of Body	Van
Colour	White		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	75.7	75	74	79
2	Boot Lid	74.2	72	78	73
3	Roof	69.5	62	74	68/75
4	Left Front Fender	77.3	75	75	82
5	Left Front Door	74.2	75	73	75
6	Center Panel Left				
7	Left Rear Door				
8	Left Back Panel	73.7	77	72	72
9	Right Front Fender	74.3	74	73	76
10	Right Front Door	72.4	70	73	74
11	Center Panel Right				
12	Right Rear Door	71.3	71	71	72
13	Right Back Panel	76.0	76	71	82

Overall Evaluation :

B

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : B		Exterior Evaluation : C	
 Diagram showing the interior of a vehicle with numbered points (1-10) and defect codes (Y3, Y3, 5) indicating areas of concern.		 Diagram showing the exterior of a vehicle with numbered points (1-17) and defect codes (A2, A2, A3, AU2, A4, U2, A3) indicating areas of concern.	
a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain		A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap	
Remarks (R) Front Seat - Grime - Medium / Ceiling - Grime - Medium		Remarks (R) Mirror - Scratch - Small / (R) Step, In-panel, Side Spoiler - Scratch & Dent - Small / (R) Rear Door, Molding - Scratch - Medium / (R) Rear Fender, Molding - Scratch & Dent - Small / (L) Rear Fender, Molding - Repair mark - Yes / (L) Rear Fender, Molding - Scratch - Large / (L) Front Door, Molding - Scratch - Small / Front Bumper, Grille, Lamps - Scratch - Small / Rear Bumper, Lamps, Panels - Scratch - Medium / Roof - Dent - Small	
Frame Evaluation : A		Functional Evaluation : A	
Remarks Defects not found		Remarks Defects not found	

Inspector Notes

With warranty booklet and spare tire. Without jack and tools. 2 keys. With LTO plate. With car alarm system