

## General Information

Date & Time: 30, May, 2025 10:26

<b>Make</b>	Honda	<b>Model</b>	Civic
<b>YOM</b>	2018	<b>Odo Meter Reading</b>	42,462
<b>Registration No.</b>	NCV2212	<b>Chassis No.</b>	MRHFC6630JT021301
<b>CC</b>	1.8	<b>Transmission</b>	CVT
<b>Fuel Type</b>	Gas	<b>Type of Body</b>	Sedan
<b>Colour</b>	White		

## Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	187.3	183	201	178
2	Boot Lid	228.3	249	202	234
3	Roof	193.2	163	162	216/232
4	Left Front Fender	121.3	125	124	115
5	Left Front Door	117.3	129	107	116
6	Center Panel Left				
7	Left Rear Door	147.0	140	147	154
8	Left Back Panel	111.6	107	115	113
9	Right Front Fender	120.0	119	120	121
10	Right Front Door	148.0	189	135	120
11	Center Panel Right				
12	Right Rear Door	179.3	259	142	137
13	Right Back Panel	163.3	155	183	152

## Overall Evaluation :

**C**

### Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

<b>Interior Evaluation :</b>	<b>B</b>	<b>Exterior Evaluation :</b>	<b>E</b>
			
<p><b>a</b> : Cut, Fray <b>d</b> : Loose, Deformed <b>k</b> : Animal Hair <b>s</b> : Smell <b>t</b> : Cigarette Burns <b>x</b> : Defective <b>y</b> : Stain</p>		<p><b>A</b> : Scratch <b>AU</b> : Scratch &amp; Dent <b>B</b> : Modified <b>C</b> : Corrosion <b>G</b> : Stone chip <b>P</b> : Faded <b>S</b> : Rust <b>SC</b> : Rust &amp; Corrosion <b>U</b> : Dent <b>X</b> : Defective <b>Y</b> : Crack, Gap</p>	
<p><b>Remarks</b> (R) Front Floor Mat - Grime - Small / (R) Front Trim - Grime - Small / (R) Rear Trim - Grime - Small / (L) Front Floor Mat - Grime - Small / (L) Front Trim - Grime - Medium</p>		<p><b>Remarks</b> Bonnet - Repair Traces - Yes / Trunk Hood, Rear Gate - Repair Traces - Yes / (R) Rear Door - Repair Traces - Yes / Roof - Repair Traces - Yes / (R) Rear Door, Molding - Scratch &amp; Dent - Large / (R) Front Door, Molding - Scratch &amp; Dent - Large / (R) Front Fender, Molding - Scratch &amp; Dent - Medium / Rear Bumper, Lamps, Panels - Scratch - Large / (L) Rear Door, Molding - Scratch - Small / (L) Step, In-panel, Side Spoiler - Scratch &amp; Dent - Large / Front Bumper, Grille, Lamps - Crack, Gap - Large / (L) Front Door, Molding - Scratch - Medium</p>	
<b>Frame Evaluation :</b>	<b>A</b>	<b>Functional Evaluation :</b>	<b>A</b>
<p><b>Remarks</b> Defects not found</p>		<p><b>Remarks</b> Spare Key - Issue - Unexist</p>	

## Inspector Notes

Without warranty booklet and tools. With spare tire, jack and seat cover. 1 key. With LTO plate.