


General Information

Date & Time: 30, May, 2025 08:25

Make	Toyota	Model	Hilux
YOM	2015	Odo Meter Reading	121,304
Registration No.	ANA1851	Chassis No.	MR0ER39G207641480
CC	2.5	Transmission	M/T
Fuel Type	Diesel	Type of Body	Pickup
Colour	Black		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	100.3	99	107	95
2	Boot Lid	99.9	98	105	97
3	Roof	107.8	101	90	122/118
4	Left Front Fender	103.9	106	109	97
5	Left Front Door	98.0	87	102	105
6	Center Panel Left				
7	Left Rear Door	99.9	105	102	93
8	Left Back Panel	106.5	98	116	106
9	Right Front Fender	103.5	96	109	106
10	Right Front Door	102.1	109	104	93
11	Center Panel Right				
12	Right Rear Door	93.5	88	94	99
13	Right Back Panel	97.6	103	105	85

Overall Evaluation :

D

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : C	Exterior Evaluation : E
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Overall Interior - Worn as per age - Yes / Ceiling - Grime - Medium / (L) Front Seat - Worn - Yes / (R) Front Seat - Worn - Yes / Rear Seat - Cut, Crack - Small / Mat Other - Grime - Small / (R) Front Floor Mat - Grime - Small / Sunvisor, Sunglass Holder - Grime - Medium	Remarks (L) Side Gate - Scratch & Dent - Large / (L) Side Gate - Repair mark - Yes / (L) Rear Door, Molding - Scratch - Large / (L) Front Door, Molding - Scratch - Large / (L) Front Fender, Molding - Scratch & Dent - Large / Front Bumper, Grille, Lamps - Repair mark - Yes / Front Bumper, Grille, Lamps - Scratch & Dent - Large / (R) Front Fender, Molding - Scratch & Dent - Large / (R) Front Door, Molding - Scratch - Small / (R) Rear Door, Molding - Scratch - Small / (R) Rear Corner Panel - Scratch & Dent - Medium / (R) Side Gate - Repair mark - Yes / (R) Side Gate - Scratch - Medium / Rear Bumper, Lamps, Panels - Scratch & Dent - Large / Rear Gate - Scratch & Dent - Small / Roof - Scratch & Dent - Small / Cab Back Panel - Dent - Small / Bonnet, Headlight - Scratch - Small
Frame Evaluation : A	Functional Evaluation : C
Remarks Defects not found	Remarks Warning Lamps - Issue - Yes / Reverse Camera - N/A - Yes / Spare Key - Issue - Unexist

Inspector Notes
Fuel Filter warning lamp. Without warranty booklet, seat cover, jack, tools and spare tire. 1 key. With LTO plate.