

General Information

Date & Time: 19, Oct, 2024 14:16

Make	Toyota	Model	Vios
YOM	2024	Mileage	4,787
Registration No.	DBN7083	Chassis No.	PA1B18F30P4234281
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Red		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	108.6	114	102	110
2	Boot Lid	106.3	101	106	112
3	Roof	98.7	96	105	93/102
4	Left Front Fender	94.2	95	95	92
5	Left Front Door	99.8	99	97	104
6	Center Panel Left				
7	Left Rear Door	100.2	103	100	98
8	Left Back Panel	110.6	120	107	105
9	Right Front Fender	107.6	106	109	108
10	Right Front Door	103.0	100	107	102
11	Center Panel Right				
12	Right Rear Door	103.6	108	102	101
13	Right Back Panel	108.6	99	107	120

Overall Evaluation :

A

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

Interior Evaluation : B	Exterior Evaluation : A
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Dashboard - Traces of Adhesive Tape - Yes / Overall Interior - Smell - Yes	Remarks (L) Front Door, Molding - Scratch - Minimal / Rear Bumper, Lamps, Panels - Scratch - Small / (R) Front Fender, Molding - Scratch - Minimal
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Reverse Camera - N/A - Yes

Inspector Notes
swirl marks and hairline scratches around the exterior.