

General Information

Date & Time: 31, May, 2025 13:11

Make	Toyota	Model	Vios
YOM	2024	Odo Meter Reading	30,903
Registration No.	NHR1240	Chassis No.	PA1B18F37P4226646
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Black		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	107.3	108	101	113
2	Boot Lid	105.6	103	107	107
3	Roof	107.5	113	104	107/106
4	Left Front Fender	96.0	94	90	104
5	Left Front Door	112.3	107	114	116
6	Center Panel Left				
7	Left Rear Door	104.9	113	102	100
8	Left Back Panel	120.0	127	119	114
9	Right Front Fender	100.9	103	97	103
10	Right Front Door	99.6	101	99	99
11	Center Panel Right				
12	Right Rear Door	106.1	100	106	113
13	Right Back Panel	109.6	109	106	114

Overall Evaluation :

C

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : C	Exterior Evaluation : D
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks (R) Front Seat - Grime - Large / (L) Front Seat - Grime - Large / Overall Interior - Worn as per age - Yes / Rear Seat - Grime - Large / Mat Other - Missing - Yes / (L) Front Floor Mat - Worked - Large</p>	<p>Remarks (L) Front Door, Molding - Scratch - Minimal / (L) Rear Door, Molding - Scratch - Small / (L) Front Fender, Molding - Scratch & Dent - Medium / Front Bumper, Grille, Lamps - Scratch - Large / (R) Front Fender, Molding - Scratch & Dent - Medium / (R) Step, In-panel, Side Spoiler - Scratch & Dent - Medium / (R) Front Door, Molding - Scratch - Minimal / (R) Rear Door, Molding - Scratch - Small / Rear Bumper, Lamps, Panels - Scratch - Small / Trunk Hood, Rear Gate - Scratch - Minimal / (L) Rear Fender, Molding - Scratch - Small / Roof - Scratch - Small / Bonnet, Headlight - Scratch - Small / (L) Mirror - Scratch, Peeled - Minimal / (R) Rear Fender, Molding - Scratch - Small</p>
Frame Evaluation : A	Functional Evaluation : A
<p>Remarks Defects not found</p>	<p>Remarks Reverse Camera - N/A - Yes / Spare Key - Issue - Unexist</p>

<p>Inspector Notes</p>
<p>with LTO plate and Jack, Sparetire and incomplete tools. no warranty booklet. scratch and crack tail light and headlight light.</p>