

General Information

Date & Time: 02, Jun, 2025 14:35

Make	Toyota	Model	Vios
YOM	2021	Odo Meter Reading	39,363
Registration No.	BAE8938	Chassis No.	PA1B18F35M4154728
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Green		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	119.3	125	103	130
2	Boot Lid	107.0	108	103	110
3	Roof	102.1	111	98	96/104
4	Left Front Fender	99.7	100	97	103
5	Left Front Door	105.7	99	117	101
6	Center Panel Left				
7	Left Rear Door	206.6	209	229	182
8	Left Back Panel	218.0	213	237	204
9	Right Front Fender	279.6	280	278	281
10	Right Front Door	104.8	110	100	105
11	Center Panel Right				
12	Right Rear Door	201.6	203	197	205
13	Right Back Panel	105.5	109	100	108

Overall Evaluation :

C

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : C	Exterior Evaluation : E
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks Trunk Room - Worked - Large / Mat Other - Missing - Yes / (R) Front Seat - Grime - Medium / (R) Front Trim - Worked - Small / (L) Front Seat - Grime - Small / (L) Front Trim - Worked - Small / Rear Seat - Grime - Medium / Ceiling - Grime - Small / (L) Rear Trim - Worked - Small / (R) Rear Trim - Worked - Small</p>	<p>Remarks (R) Front Fender - Repair Traces - Yes / (L) Rear Door - Repair Traces - Yes / (L) Rear Fender - Repair Traces - Yes / (R) Rear Door - Repair Traces - Yes / (R) Front Fender, Molding - Repair mark - Yes / (R) Rear Door, Molding - Repair mark - Yes / (L) Rear Fender, Molding - Repair mark - Yes / (L) Rear Door, Molding - Repair mark - Yes / Front Bumper, Grille, Lamps - Repair mark - Yes / Member (Bolted) - Dent - Yes / (R) Rear Door, Molding - Scratch & Dent - Medium / (R) Front Fender, Molding - Scratch & Dent - Small / (R) Step, In-panel, Side Spoiler - Scratch & Dent - Small / (R) Front Door, Molding - Scratch - Medium / (R) Rear Fender, Molding - Scratch - Small / Roof - Scratch & Dent - Minimal / Rear Bumper, Lamps, Panels - Scratch - Medium / (L) Rear Fender, Molding - Scratch - Small / (L) Rear Door, Molding - Scratch - Medium / (L) Front Door, Molding - Scratch - Medium / (L) Front Fender, Molding - Scratch - Medium / Front Bumper, Grille, Lamps - Scratch - Medium / Bonnet, Headlight - Scratch - Medium / (R) Mirror - Scratch - Minimal</p>
Frame Evaluation : A	Functional Evaluation : A
<p>Remarks Defects not found</p>	<p>Remarks Reverse Camera - N/A - Yes / Spare Key - Issue - Unexist</p>

<p>Inspector Notes</p>
<p>with LTO plate, with warranty booklet, with jack, no tools, no spare tire, no reverse camera, scratches on tail lights and headlights</p>