

General Information

Date & Time: 09, Jun, 2025 13:51

Make	Toyota	Model	Vios
YOM	2022	Odo Meter Reading	62,319
Registration No.	NFP5918	Chassis No.	PA1B18F34N4191612
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Red Mica Metallic		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	97.5	96	94	103
2	Boot Lid	104.3	106	102	105
3	Roof	95.0	99	92	95/94
4	Left Front Fender	101.7	104	103	98
5	Left Front Door	105.0	106	109	100
6	Center Panel Left				
7	Left Rear Door	98.3	99	102	94
8	Left Back Panel	106.2	119	96	104
9	Right Front Fender	102.2	104	106	97
10	Right Front Door	93.8	95	93	94
11	Center Panel Right				
12	Right Rear Door	96.2	94	95	100
13	Right Back Panel	100.5	95	98	109

Overall Evaluation :

C

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : C	Exterior Evaluation : E
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks Ceiling - Grime - Medium / (R) Front Trim - Grime - Small / (R) Front Seat - Grime - Large / (R) Front Floor Mat - Missing - Yes / Mat Other - Missing - Yes / (L) Front Floor Mat - Missing - Yes / Rear Seat - Grime - Medium / (L) Front Seat - Grime - Medium / (L) Front Trim - Grime - Medium</p>	<p>Remarks (L) Front Fender, Molding - Scratch & Dent - Large / (L) Front Door, Molding - Scratch & Dent - Small / (L) Rear Door, Molding - Scratch & Dent - Large / Front Bumper, Grille, Lamps - Scratch & Dent - Large / (R) Mirror - Scratch - Minimal / (L) Rear Fender, Molding - Scratch & Dent - Large / Rear Bumper, Lamps, Panels - Scratch & Dent - Large / Trunk Hood, Rear Gate - Scratch & Dent - Small / (R) Rear Fender, Molding - Scratch & Dent - Large / (R) Rear Door, Molding - Scratch & Dent - Large / (R) Front Door, Molding - Scratch & Dent - Medium</p>
Frame Evaluation : A	Functional Evaluation : B
<p>Remarks Defects not found</p>	<p>Remarks Battery - Weak - Yes / Reverse Camera - N/A - Yes / Spare Key - Issue - Unexist</p>

<p>Inspector Notes</p>
<p>Possible flooding. crack right taillight. trunk floor missing. with warranty booklet and spare tire. without jack, tools and seat cover. 1key. with LTO plate</p>