

General Information

Date & Time: 07, Jun, 2025 10:32

Make	Toyota	Model	Vios
YOM	2022	Odo Meter Reading	11,926
Registration No.	BAC8395	Chassis No.	PA1B18F31N4181233
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Red Mica Metallic		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	107.6	106	107	110
2	Boot Lid	109.0	104	112	111
3	Roof	98.5	104	95	94/101
4	Left Front Fender	97.2	96	99	96
5	Left Front Door	101.7	101	106	98
6	Center Panel Left				
7	Left Rear Door	98.6	100	97	99
8	Left Back Panel	106.6	116	102	102
9	Right Front Fender	89.8	92	90	88
10	Right Front Door	94.3	94	93	97
11	Center Panel Right				
12	Right Rear Door	94.3	95	90	99
13	Right Back Panel	97.2	100	92	100

Overall Evaluation :

C

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : B	Exterior Evaluation : E
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks Mat Other - Missing - Yes / (R) Front Trim - Grime - Small / (L) Front Trim - Grime - Small / Ceiling - Grime - Small</p>	<p>Remarks (R) Front Fender, Molding - Scratch & Dent - Medium / (R) Front Door, Molding - Scratch & Dent - Large / (R) Rear Door, Molding - Scratch - Large / (R) Rear Fender, Molding - Scratch & Dent - Medium / Rear Bumper, Lamps, Panels - Scratch - Large / (L) Rear Fender, Molding - Scratch & Dent - Medium / (L) Rear Door, Molding - Scratch - Small / (L) Front Door, Molding - Scratch & Dent - Medium / (L) Front Fender, Molding - Scratch & Dent - Medium / Bonnet, Headlight - Scratch & Dent - Small / Front Bumper, Grille, Lamps - Scratch - Small / Trunk Hood, Rear Gate - Scratch - Minimal</p>
Frame Evaluation : A	Functional Evaluation : A
<p>Remarks Defects not found</p>	<p>Remarks Reverse Camera - N/A - Yes</p>

<p>Inspector Notes</p>
<p>With warranty booklet, spare tire, seat cover, jack and tools. 3 keys. LTO plate not installed in this unit.</p>