

General Information

Date & Time: 05, Jun, 2025 18:02

Make	Toyota	Model	Lite Ace
YOM	2024	Odo Meter Reading	28,664
Registration No.	NHS5215	Chassis No.	MHKU3FE10RK007508
CC	1.5	Transmission	M/T
Fuel Type	Gas	Type of Body	Van
Colour	White		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	65.3	68	70	59
2	Boot Lid	57.0	72	51	49
3	Roof	57.3	48	61	52/69
4	Left Front Fender	55.9	48	56	64
5	Left Front Door	64.8	71	65	59
6	Center Panel Left				
7	Left Rear Door				
8	Left Back Panel	70.7	63	85	64
9	Right Front Fender	63.1	71	61	57
10	Right Front Door	61.0	60	62	62
11	Center Panel Right				
12	Right Rear Door				
13	Right Back Panel	79.1	81	93	63

Overall Evaluation :

B

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : B	Exterior Evaluation : C
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
Remarks Ceiling - Grime - Medium	Remarks Front Bumper, Grille, Lamps - Scratch - Large / (R) Mirror - Scratch - Minimal / (R) Front Door, Molding - Scratch - Small / Roof - Dent - Medium / (R) Side Gate - Scratch - Medium / (L) Side Gate - Scratch - Medium / Rear Bumper, Lamps, Panels - Scratch - Medium / (L) Front Door, Molding - Scratch - Small
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Reverse Camera - N/A - Yes / Spare Key - Issue - Unexist

Inspector Notes
Without warranty booklet. with Spare tire, jack and tools. 1 key. with LTO plate.