

General Information

Date & Time: 05, Jun, 2025 12:56

Make	Toyota	Model	Vios
YOM	2024	Odo Meter Reading	3,421
Registration No.	CCC6192	Chassis No.	PA1B18F31R4242117
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Black		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	103.5	102	100	109
2	Boot Lid	99.8	98	97	105
3	Roof	98.8	101	100	95/100
4	Left Front Fender	94.5	94	97	94
5	Left Front Door	96.8	97	100	94
6	Center Panel Left				
7	Left Rear Door	98.7	102	98	96
8	Left Back Panel	109.6	125	101	103
9	Right Front Fender	99.4	100	99	99
10	Right Front Door	107.3	110	110	102
11	Center Panel Right				
12	Right Rear Door	100.5	96	99	107
13	Right Back Panel	106.3	103	106	110

Overall Evaluation :

B

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : B	Exterior Evaluation : D
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks (R) Front Trim - Grime - Small / (R) Front Floor Mat - Grime - Small / Ceiling - Grime - Minimal / (L) Front Trim - Grime - Medium</p>	<p>Remarks (L) Mirror - Scratch - Minimal / (L) Front Door, Molding - Scratch - Medium / (L) Rear Door, Molding - Scratch - Medium / (R) Front Door, Molding - Scratch - Large / (R) Rear Fender, Molding - Scratch - Medium / (R) Front Fender, Molding - Scratch - Small / Rear Bumper, Lamps, Panels - Scratch - Small / Trunk Hood, Rear Gate - Scratch - Medium / (L) Front Fender, Molding - Scratch - Small / Front Bumper, Grille, Lamps - Scratch - Medium / (R) Rear Door, Molding - Scratch - Medium</p>
Frame Evaluation : A	Functional Evaluation : A
<p>Remarks Defects not found</p>	<p>Remarks Defects not found</p>

<p>Inspector Notes</p>
<p>With warranty booklet, spare tire, seat cover, jack but incomplete tools. 3 keys. with LTO plate.</p>