

General Information

Date & Time: 29, Oct, 2024 08:46

Make	Toyota	Model	Vios
YOM	2024	Mileage	6,086
Registration No.	DBN4907	Chassis No.	PA1B18F34P4231478
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Green		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	116.6	118	113	119
2	Boot Lid	118.3	111	120	124
3	Roof	105.2	107	100	105/109
4	Left Front Fender	112.3	114	117	106
5	Left Front Door	110.0	107	104	119
6	Center Panel Left				
7	Left Rear Door	121.3	128	117	119
8	Left Back Panel	121.6	134	118	113
9	Right Front Fender	110.6	110	107	115
10	Right Front Door	109.3	114	106	108
11	Center Panel Right				
12	Right Rear Door	106.6	105	106	109
13	Right Back Panel	125.3	120	123	133

Overall Evaluation :

A

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

Interior Evaluation : A	Exterior Evaluation : A
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
Remarks Defects not found	Remarks Front Bumper, Grille, Lamps - Scratch - Small / (R) Rear Door, Molding - Scratch - Small / (R) Mirror - Scratch, Peeled - Minimal / Trunk Hood, Rear Gate - Dent - Small
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Reverse Camera - N/A - Yes / Spare Key - Issue - Unexist

Inspector Notes
hairline and swirl marks around the exterior/ has interior figurines and accessory on the dashboard/ no reverse camera