

General Information

Date & Time: 07, Jun, 2025 09:37

Make	Toyota	Model	Hilux
YOM	2023	Odo Meter Reading	80,723
Registration No.	BAF4169	Chassis No.	MR0AB8DDXP5036108
CC	2.4	Transmission	A/T
Fuel Type	Diesel	Type of Body	Pickup
Colour	Gray		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	118.0	118	119	117
2	Boot Lid	112.3	101	125	111
3	Roof	117.5	110	109	127/124
4	Left Front Fender	116.6	125	111	114
5	Left Front Door	107.3	111	108	103
6	Center Panel Left				
7	Left Rear Door	104.3	108	105	100
8	Left Back Panel	100.5	100	101	101
9	Right Front Fender	118.3	115	113	127
10	Right Front Door	106.6	105	106	109
11	Center Panel Right				
12	Right Rear Door	105.0	102	103	110
13	Right Back Panel	105.0	103	106	106

Overall Evaluation :

B

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : B	Exterior Evaluation : D
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks Ceiling - Grime - Medium / (R) Front Seat - Grime - Medium / Rear Seat - Grime - Medium / (L) Front Seat - Grime - Medium</p>	<p>Remarks (L) Mirror - Scratch - Minimal / Rear Gate - Dent - Medium / (R) Side Gate - Scratch - Medium / (R) Rear Door, Molding - Scratch - Small / Front Bumper, Grille, Lamps - Scratch & Dent - Medium / Roof - Scratch - Minimal / (L) Front Fender, Molding - Scratch - Small / (L) Rear Door, Molding - Scratch & Dent - Small / (L) Front Door, Molding - Scratch - Small / (L) Side Gate - Scratch & Dent - Medium / Cab Back Panel - Scratch - Small / Rear Bumper, Lamps, Panels - Scratch - Small / (R) Front Fender, Molding - Scratch - Small / (L) Center Panel - Scratch - Medium</p>
Frame Evaluation : A	Functional Evaluation : A
<p>Remarks Defects not found</p>	<p>Remarks Spare Key - Issue - Unexist</p>

<p>Inspector Notes</p>
<p>With warranty booklet, spare tire, jack and tools. 1 key. with LTO plate. without seat cover.</p>