

General Information

Date & Time: 12, Nov, 2024 08:01

Make	Toyota	Model	Vios
YOM	2024	Mileage	8,669
Registration No.	NFR6522	Chassis No.	PA1B18F34R4252141
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Red		

Body / Panel Condition




#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	123.0	130	119	120
2	Boot Lid	131.0	128	137	128
3	Roof	112.2	121	108	109/111
4	Left Front Fender	114.3	115	117	111
5	Left Front Door	112.0	115	112	109
6	Center Panel Left				
7	Left Rear Door	125.3	139	122	115
8	Left Back Panel	123.6	127	123	121
9	Right Front Fender	114.6	104	104	136
10	Right Front Door	107.0	106	104	111
11	Center Panel Right				
12	Right Rear Door	108.6	103	104	119
13	Right Back Panel	114.6	105	113	126

Overall Evaluation :

A

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

Interior Evaluation : A	Exterior Evaluation : C
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks (L) Front Floor Lag - Cut, Crack - Small	Remarks Front Bumper, Grille, Lamps - Scratch - Medium / (L) Front Fender, Molding - Scratch - Small / (L) Mirror - Scratch - Minimal / (L) Front Door, Molding - Dent - Small / Trunk Hood, Rear Gate - Scratch - Minimal / (R) Rear Fender, Molding - Scratch - Medium / (R) Rear Door, Molding - Scratch - Medium / (R) Front Door, Molding - Scratch - Medium / (R) Front Fender, Molding - Scratch - Medium
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Defects not found

Inspector Notes
hairline scratches around the exterior.