

## General Information

Date & Time: 07, Jun, 2025 12:33

<b>Make</b>	Toyota	<b>Model</b>	Vios
<b>YOM</b>	2025	<b>Odo Meter Reading</b>	16,804
<b>Registration No.</b>	NKF7838	<b>Chassis No.</b>	PA1B18F31R4270368
<b>CC</b>	1.3	<b>Transmission</b>	CVT
<b>Fuel Type</b>	Gas	<b>Type of Body</b>	Sedan
<b>Colour</b>	Black		

## Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	<b>114.0</b>	116	109	117
2	Boot Lid	<b>103.8</b>	100	102	110
3	Roof	<b>100.1</b>	105	99	100/97
4	Left Front Fender	<b>98.2</b>	99	98	98
5	Left Front Door	<b>106.6</b>	108	108	104
6	Center Panel Left				
7	Left Rear Door	<b>107.3</b>	111	106	105
8	Left Back Panel	<b>111.6</b>	123	108	104
9	Right Front Fender	<b>102.7</b>	99	107	102
10	Right Front Door	<b>106.6</b>	99	121	100
11	Center Panel Right				
12	Right Rear Door	<b>102.0</b>	105	98	103
13	Right Back Panel	<b>104.3</b>	105	100	108

Overall Evaluation :

**B**

### Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

<b>Interior Evaluation :</b> <span style="float: right;"><b>C</b></span>	<b>Exterior Evaluation :</b> <span style="float: right;"><b>C</b></span>
 <p><b>a</b> : Cut, Fray <b>d</b> : Loose, Deformed <b>k</b> : Animal Hair <b>s</b> : Smell <b>t</b> : Cigarette Burns <b>x</b> : Defective <b>y</b> : Stain</p>	 <p><b>A</b> : Scratch <b>AU</b> : Scratch &amp; Dent <b>B</b> : Modified <b>C</b> : Corrosion <b>G</b> : Stone chip <b>P</b> : Faded <b>S</b> : Rust <b>SC</b> : Rust &amp; Corrosion <b>U</b> : Dent <b>X</b> : Defective <b>Y</b> : Crack, Gap</p>
<p><b>Remarks</b> Ceiling - Grime - Minimal / (R) Front Trim - Grime - Small / (R) Front Seat - Grime - Medium / (R) Front Floor Mat - Grime - Medium / Rear Seat - Grime - Medium / Mat Other - Grime - Small / (L) Front Seat - Grime - Medium / (L) Front Floor Mat - Grime - Minimal</p>	<p><b>Remarks</b> (L) Rear Fender, Molding - Scratch &amp; Dent - Small / (L) Front Door, Molding - Scratch - Small / (L) Rear Door, Molding - Scratch - Small / (L) Front Fender, Molding - Scratch - Small / Front Bumper, Grille, Lamps - Scratch - Medium / Bonnet, Headlight - Scratch - Medium / (R) Rear Fender, Molding - Scratch &amp; Dent - Small / (R) Mirror - Scratch - Small / Trunk Hood, Rear Gate - Scratch &amp; Dent - Small / Rear Bumper, Lamps, Panels - Scratch - Medium / Roof - Scratch - Minimal / (R) Rear Door, Molding - Scratch &amp; Dent - Small</p>
<b>Frame Evaluation :</b> <span style="float: right;"><b>A</b></span>	<b>Functional Evaluation :</b> <span style="float: right;"><b>A</b></span>
<p><b>Remarks</b> Defects not found</p>	<p><b>Remarks</b> Spare Key - Issue - Unexist</p>

<p><b>Inspector Notes</b></p>
<p>trunk door closing issue. with warranty booklet, spare tire and jack. without tools and seat cover. 1 key. with LTO plate</p>