

General Information

Date & Time: 07, Jun, 2025 13:02

Make	Toyota	Model	Innova
YOM	2025	Odo Meter Reading	64,158
Registration No.	BAG7535	Chassis No.	PA2JA8EM6R0148503
CC	2.8	Transmission	A/T
Fuel Type	Diesel	Type of Body	MPV
Colour	Red Mica Metallic		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	116.6	111	123	116
2	Boot Lid	97.9	100	92	102
3	Roof	95.4	95	96	94/98
4	Left Front Fender	100.6	105	103	94
5	Left Front Door	100.1	94	102	104
6	Center Panel Left				
7	Left Rear Door	102.0	108	100	98
8	Left Back Panel	99.7	98	102	99
9	Right Front Fender	105.2	99	115	102
10	Right Front Door	101.6	102	103	100
11	Center Panel Right				
12	Right Rear Door	104.6	100	103	111
13	Right Back Panel	109.3	115	108	105

Overall Evaluation :

C

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : C	Exterior Evaluation : D
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks Ceiling - Grime - Medium / (R) Front Floor Mat - Grime - Large / (R) Front Trim - Grime - Small / (R) Rear Trim - Grime - Small / Mat Other - Grime - Large / (L) Rear Trim - Grime - Small / (L) Front Floor Mat - Cut, Crack - Small</p>	<p>Remarks (L) Front Fender, Molding - Scratch & Dent - Large / Front Bumper, Grille, Lamps - Scratch & Dent - Large / (R) Front Fender, Molding - Scratch - Medium / (R) Rear Door, Molding - Scratch - Medium / (R) Front Door, Molding - Scratch - Small / (R) Rear Fender, Molding - Scratch - Medium / Rear Bumper, Lamps, Panels - Scratch - Small / (L) Rear Fender, Molding - Scratch - Minimal / (L) Rear Door, Molding - Scratch - Small / (L) Mirror - Scratch - Minimal / (L) Front Door, Molding - Scratch - Minimal</p>
Frame Evaluation : A	Functional Evaluation : A
<p>Remarks Defects not found</p>	<p>Remarks Defects not found</p>

<p>Inspector Notes</p>
<p>With warranty booklet, spare tire, seat cover, jack and tools. 2 keys. with LTO plate</p>