

## General Information

Date & Time: 05, Jun, 2025 18:47

<b>Make</b>	Toyota	<b>Model</b>	Vios
<b>YOM</b>	2025	<b>Odo Meter Reading</b>	6,130
<b>Registration No.</b>	BAG7277	<b>Chassis No.</b>	PA1B18F36R4279051
<b>CC</b>	1.3	<b>Transmission</b>	CVT
<b>Fuel Type</b>	Gas	<b>Type of Body</b>	Sedan
<b>Colour</b>	Blue		

## Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	107.3	108	105	109
2	Boot Lid	96.6	93	90	107
3	Roof	99.7	106	98	96/99
4	Left Front Fender	93.4	95	98	87
5	Left Front Door	96.6	98	98	95
6	Center Panel Left				
7	Left Rear Door	102.3	104	102	101
8	Left Back Panel	98.4	108	90	98
9	Right Front Fender	103.6	103	104	104
10	Right Front Door	106.6	110	109	101
11	Center Panel Right				
12	Right Rear Door	106.6	106	104	110
13	Right Back Panel	107.9	100	102	122

**Overall Evaluation :**

**B**

### Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

<b>Interior Evaluation :</b> <span style="float: right;"><b>B</b></span>	<b>Exterior Evaluation :</b> <span style="float: right;"><b>C</b></span>
 <p><b>a</b> : Cut, Fray <b>d</b> : Loose, Deformed <b>k</b> : Animal Hair <b>s</b> : Smell <b>t</b> : Cigarette Burns <b>x</b> : Defective <b>y</b> : Stain</p>	 <p><b>A</b> : Scratch <b>AU</b> : Scratch &amp; Dent <b>B</b> : Modified <b>C</b> : Corrosion <b>G</b> : Stone chip <b>P</b> : Faded <b>S</b> : Rust <b>SC</b> : Rust &amp; Corrosion <b>U</b> : Dent <b>X</b> : Defective <b>Y</b> : Crack, Gap</p>
<p><b>Remarks</b> Ceiling - Grime - Minimal / (R) Front Trim - Grime - Small / (R) Front Seat - Grime - Small / (L) Front Seat - Grime - Small / (L) Front Trim - Grime - Small</p>	<p><b>Remarks</b> Bonnet, Headlight - Scratch &amp; Dent - Minimal / (R) Front Door, Molding - Scratch &amp; Dent - Minimal / (R) Rear Fender, Molding - Scratch - Medium / Rear Bumper, Lamps, Panels - Scratch - Small / (L) Rear Fender, Molding - Scratch - Large / (L) Front Door, Molding - Scratch - Minimal / Front Bumper, Grille, Lamps - Scratch &amp; Dent - Small / Roof - Scratch - Medium</p>
<b>Frame Evaluation :</b> <span style="float: right;"><b>A</b></span>	<b>Functional Evaluation :</b> <span style="float: right;"><b>A</b></span>
<p><b>Remarks</b> Defects not found</p>	<p><b>Remarks</b> Spare Key - Issue - Unexist</p>

<p><b>Inspector Notes</b></p>
<p>With warranty booklet, spare tire, jack and tools. without seat cover. 1 key. with LTO plate</p>