

General Information

Date & Time: 07, Jun, 2025 11:04

Make	Toyota	Model	Vios
YOM	2020	Odo Meter Reading	100,775
Registration No.	IAD7041	Chassis No.	PA1B18F31L4116718
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Red Mica Metallic		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	100.6	100	101	101
2	Boot Lid	101.3	100	100	104
3	Roof	96.3	103	91	94/97
4	Left Front Fender	94.3	96	95	92
5	Left Front Door	94.1	95	92	96
6	Center Panel Left				
7	Left Rear Door	103.8	112	103	97
8	Left Back Panel	100.6	107	97	98
9	Right Front Fender	95.2	95	94	97
10	Right Front Door	96.9	98	95	98
11	Center Panel Right				
12	Right Rear Door	97.9	100	94	100
13	Right Back Panel	100.0	99	95	107

Overall Evaluation :

B

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : B	Exterior Evaluation : D
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks Ceiling - Grime - Medium / (R) Front Trim - Grime - Medium / (R) Front Floor Mat - Grime - Small / Overall Interior - Smell - Yes</p>	<p>Remarks (L) Rear Fender, Molding - Scratch & Dent - Small / (L) Rear Door, Molding - Scratch - Medium / Rear Bumper, Lamps, Panels - Scratch & Dent - Large / Trunk Hood, Rear Gate - Scratch - Minimal / (L) Front Door, Molding - Scratch & Dent - Minimal / (L) Front Fender, Molding - Scratch - Small / Front Bumper, Grille, Lamps - Scratch - Medium / Bonnet, Headlight - Scratch - Small / (R) Mirror - Scratch - Minimal / (R) Rear Door, Molding - Scratch - Small / (R) Front Door, Molding - Scratch - Medium / (R) Rear Fender, Molding - Scratch & Dent - Small / Roof - Dent - Minimal</p>
Frame Evaluation : A	Functional Evaluation : A
<p>Remarks Defects not found</p>	<p>Remarks Reverse Camera - N/A - Yes / Spare Key - Issue - Unexist</p>

<p>Inspector Notes</p>
<p>Possible flooding. with warranty booklet, seat cover and spare tire. without jack and tools. 1 key. with LTO plate</p>