

General Information

Date & Time: 09, Jun, 2025 08:21

Make	Toyota	Model	Vios
YOM	2017	Odo Meter Reading	74,321
Registration No.	NAZ9577	Chassis No.	PA1B19F36H4038305
CC	1.3	Transmission	A/T
Fuel Type	Gas	Type of Body	Sedan
Colour	Silver		

Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	106.6	111	103	106
2	Boot Lid	117.3	118	113	121
3	Roof	110.0	108	111	110/111
4	Left Front Fender	104.3	105	105	103
5	Left Front Door	112.6	120	115	103
6	Center Panel Left				
7	Left Rear Door	114.0	108	113	121
8	Left Back Panel	120.0	126	113	121
9	Right Front Fender	116.0	122	115	111
10	Right Front Door	114.6	110	117	117
11	Center Panel Right				
12	Right Rear Door	113.3	113	116	111
13	Right Back Panel	119.3	105	133	120

Overall Evaluation :

D

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : C	Exterior Evaluation : E
<p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	<p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks Ceiling - Grime - Large / (R) Front Seat - Grime - Medium / Rear Seat - Grime - Medium / (L) Front Floor Mat - Cut, Crack - Medium / (L) Front Seat - Grime - Small</p>	<p>Remarks (L) Rear Door, Molding - Repair mark - Yes / Rear Bumper, Lamps, Panels - Repair mark - Yes / Front Bumper, Grille, Lamps - Scratch & Dent - Large / (L) Front Fender, Molding - Scratch & Dent - Medium / (L) Mirror - Scratch - Medium / (R) Front Fender, Molding - Scratch & Dent - Large / (R) Mirror - Scratch - Small / (L) Rear Door, Molding - Scratch - Medium / (L) Step, In-panel, Side Spoiler - Scratch - Small / Trunk Hood, Rear Gate - Scratch & Dent - Minimal / Rear Bumper, Lamps, Panels - Scratch & Dent - Large / (R) Rear Fender, Molding - Repair mark - Yes / (R) Rear Fender, Molding - Scratch - Medium / (R) Front Door, Molding - Scratch - Small / (R) Rear Door, Molding - Scratch & Dent - Medium / Roof - Dent - Small</p>
Frame Evaluation : A	Functional Evaluation : C
<p>Remarks Defects not found</p>	<p>Remarks Retractable Mirror - Issue - Yes / Power Window (each) - Stuck, Gap - Yes / Reverse Camera - N/A - Yes / Lamps (Brake, Tail, Fog) - Issue - Yes / Spare Key - Issue - Unexist</p>

<p>Inspector Notes</p>
<p>Without warranty booklet, spare tire, jack, tools and seat cover. 1 key. without LTO plate. grime at trunk floor.</p>