

General Information

Date & Time: 29, Oct, 2024 10:10

Make	Toyota	Model	Vios
YOM	2024	Mileage	6,541
Registration No.	NHM1748	Chassis No.	PA1B18F3XP4235843
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Green		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	118.0	122	116	116
2	Boot Lid	118.3	115	120	120
3	Roof	109.1	117	107	99/114
4	Left Front Fender	105.5	111	99	107
5	Left Front Door	109.0	103	104	120
6	Center Panel Left				
7	Left Rear Door	115.0	112	116	117
8	Left Back Panel	112.6	121	113	104
9	Right Front Fender	107.6	104	107	112
10	Right Front Door	113.0	115	107	117
11	Center Panel Right				
12	Right Rear Door	111.3	108	113	113
13	Right Back Panel	115.6	107	107	133

Overall Evaluation :

A

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

Interior Evaluation : A	Exterior Evaluation : C
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Defects not found	Remarks (L) Front Door, Molding - Scratch - Medium / Front Bumper, Grille, Lamps - Scratch & Dent - Large / (R) Front Door, Molding - Scratch & Dent - Small / (R) Rear Door, Molding - Dent - Small / (R) Mirror - Scratch, Peeled - Minimal / Trunk Hood, Rear Gate - Dent - Minimal / (L) Mirror - Scratch, Peeled - Minimal / (L) Front Wheel, Cover - Scratch, Corrosion - Small / (L) Rear Wheel, Cover - Scratch, Corrosion - Small / (R) Rear Wheel, Cover - Scratch, Corrosion - Small / (R) Front Wheel, Cover - Scratch, Corrosion - Small
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Reverse Camera - N/A - Yes / Spare Key - Issue - Unexist

Inspector Notes
reverse camera notmworking/ no retractable side mirror / swirl marks and hairline scratches present/