

General Information

Date & Time: 07, Jun, 2025 14:51

Make	Suzuki	Model	Ertiga
YOM	2021	Odo Meter Reading	50,090
Registration No.	CBM2669	Chassis No.	MHYNC22S9MJ106434
CC	1.5	Transmission	M/T
Fuel Type	Gas	Type of Body	MPV
Colour	White		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	93.6	96	90	95
2	Boot Lid	92.9	87	99	92
3	Roof	97.8	90	101	101/100
4	Left Front Fender	89.6	94	88	86
5	Left Front Door	98.7	100	95	102
6	Center Panel Left				
7	Left Rear Door	98.7	106	95	95
8	Left Back Panel	91.8	95	97	84
9	Right Front Fender	220.0	123	136	401
10	Right Front Door	126.0	134	120	124
11	Center Panel Right				
12	Right Rear Door	118.3	115	116	124
13	Right Back Panel	114.3	112	115	116

Overall Evaluation :

A

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : B	Exterior Evaluation : B
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks (R) Front Seat - Grime - Medium / Rear Seat - Grime - Medium / (L) Front Seat - Grime - Small / Dashboard - Traces of Adhesive Tape - Yes / Sunvisor, Sunglass Holder - Crinkle - Small</p>	<p>Remarks (R) Front Fender - Repair Traces - Yes / (R) Rear Fender, Molding - Scratch - Minimal / (R) Mirror - Scratch - Small / (R) Front Fender, Molding - Scratch - Small / (R) Rear Door, Molding - Scratch - Minimal / Rear Bumper, Lamps, Panels - Scratch - Minimal / Trunk Hood, Rear Gate - Scratch - Minimal / (L) Rear Door, Molding - Scratch & Dent - Small / (L) Front Door, Molding - Scratch - Small / (L) Mirror - Scratch - Minimal / Front Bumper, Grille, Lamps - Scratch - Medium / Roof - Scratch - Minimal / Front Windshield - Scratch, Stone chip - Small</p>
Frame Evaluation : A	Functional Evaluation : A
<p>Remarks Defects not found</p>	<p>Remarks Reverse Camera - N/A - Yes</p>

<p>Inspector Notes</p>
<p>With warranty booklet, spare tire, jack and tools. Without seat cover. 2 keys. with LTO plate.</p>