

General Information

Date & Time: 29, Oct, 2024 10:33

Make	Toyota	Model	Vios
YOM	2024	Mileage	6,545
Registration No.	CCD3278	Chassis No.	PA1B18F31R4250315
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Red		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	118.3	126	110	119
2	Boot Lid	114.3	113	109	121
3	Roof	122.5	132	110	121/127
4	Left Front Fender	109.6	116	109	104
5	Left Front Door	105.0	105	105	105
6	Center Panel Left				
7	Left Rear Door	112.6	118	111	109
8	Left Back Panel	116.3	122	117	110
9	Right Front Fender	117.3	117	115	120
10	Right Front Door	114.3	115	115	113
11	Center Panel Right				
12	Right Rear Door	122.3	118	120	129
13	Right Back Panel	113.0	113	110	116

Overall Evaluation :

A

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

Interior Evaluation : B	Exterior Evaluation : B
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Overall Interior - Smell - Yes / Trunk Room - Loose, Deformed, Grime - Small	Remarks Bonnet, Headlight - Dent - Minimal / Rear Bumper, Lamps, Panels - Scratch - Medium / (R) Rear Door, Molding - Scratch - Small
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Spare Key - Issue - Unexist

Inspector Notes

swirlmarks and hairline scratches around the exterior. scratch at the left rearbumper.