


General Information

Date & Time: 20, Jun, 2025 15:57

Make	Toyota	Model	Raize
YOM	2022	Odo Meter Reading	31,075
Registration No.	EAF2236	Chassis No.	MHKAA1BA5NJ044080
CC	1.0	Transmission	CVT
Fuel Type	Gas	Type of Body	SUV
Colour	White		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	127.6	128	140	115
2	Boot Lid	126.0	123	137	118
3	Roof	127.7	133	142	118/118
4	Left Front Fender	130.3	125	138	128
5	Left Front Door	142.0	152	143	131
6	Center Panel Left				
7	Left Rear Door	133.3	133	132	135
8	Left Back Panel	125.6	120	124	133
9	Right Front Fender	140.0	141	155	124
10	Right Front Door	138.6	132	139	145
11	Center Panel Right				
12	Right Rear Door	135.3	134	131	141
13	Right Back Panel	129.6	122	129	138

Overall Evaluation :

A

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : A	Exterior Evaluation : B
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks Rear Seat - Grime - Small / (R) Front Seat - Grime - Small / (L) Front Seat - Grime - Small / Ceiling - Grime - Small</p>	<p>Remarks Rear Bumper, Lamps, Panels - Scratch - Small / Front Bumper, Grille, Lamps - Scratch - Medium / (L) Rear Door, Molding - Dent - Small / (L) Front Door, Molding - Scratch - Minimal / (R) Rear Door, Molding - Scratch - Small / Roof - Scratch - Small / (R) Front Door, Molding - Scratch - Minimal / Trunk Hood, Rear Gate - Scratch - Minimal</p>
Frame Evaluation : A	Functional Evaluation : A
<p>Remarks Defects not found</p>	<p>Remarks Spare Key - Issue - Unexist</p>

<p>Inspector Notes</p>
<p>with LTO plate/with spare tire/with warranty booklet/No jack and tools</p>