

General Information

Date & Time: 29, Oct, 2024 09:40

Make	Toyota	Model	Vios
YOM	2024	Mileage	4,223
Registration No.	NFR9717	Chassis No.	PA1B18F35R4259535
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Black		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	114.6	116	114	114
2	Boot Lid	107.6	103	108	112
3	Roof	104.9	114	100	104/102
4	Left Front Fender	99.3	100	98	100
5	Left Front Door	101.3	104	100	100
6	Center Panel Left				
7	Left Rear Door	115.0	115	121	109
8	Left Back Panel	110.0	117	108	105
9	Right Front Fender	105.0	102	104	109
10	Right Front Door	99.3	97	102	99
11	Center Panel Right				
12	Right Rear Door	107.0	110	106	105
13	Right Back Panel	107.3	106	104	112

Overall Evaluation :

A

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

Interior Evaluation : A	Exterior Evaluation : A
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Trunk Room - Loose, Deformed, Grime - Small	Remarks (L) Step, In-panel, Side Spoiler - Scratch - Small / (R) Rear Door, Molding - Scratch & Dent - Small / Rear Bumper, Lamps, Panels - Scratch - Small / Bonnet, Headlight - Scratch - Small
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Spare Key - Issue - Unexist

Inspector Notes
swirlmarks and hairline scratches around the exterior.