

General Information

Date & Time: 14, Jun, 2025 12:53

Make	Isuzu	Model	Traviz
YOM	2022	Odo Meter Reading	82,724
Registration No.	CAW6278	Chassis No.	MHCPHR54DMJ506720
CC	2.5	Transmission	M/T
Fuel Type	Diesel	Type of Body	Van
Colour	White		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	66.0	80	57	61
2	Boot Lid	120.0	128	115	117
3	Roof	72.5	59	71	63/97
4	Left Front Fender	64.1	62	64	67
5	Left Front Door	54.3	55	54	54
6	Center Panel Left				
7	Left Rear Door				
8	Left Back Panel	146.6	115	193	132
9	Right Front Fender	76.4	79	76	75
10	Right Front Door	65.2	64	66	66
11	Center Panel Right				
12	Right Rear Door				
13	Right Back Panel	163.3	143	203	144

Overall Evaluation :

C

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : C	Exterior Evaluation : D
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Rear Seat - Partially Missing - Yes / (R) Front Seat - Grime - Medium / Ceiling - Grime - Large	Remarks (L) Rear Corner Panel - Repair Traces - Yes / (R) Side Gate - Scratch & Dent - Large / Front Bumper, Grille, Lamps - Scratch - Large / (L) Front Door, Molding - Scratch - Small / (L) Mirror - Scratch - Small / (R) Mirror - Scratch - Small / (R) Front Door, Molding - Scratch & Dent - Small / Rear Gate - Scratch & Dent - Small / Rear Bumper, Lamps, Panels - Scratch & Dent - Medium / Roof - Dent - Small / (L) Side Gate - Scratch & Dent - Medium
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Audio, Radio - Issue - Yes / Reverse Camera - N/A - Yes / Spare Key - Issue - Unexist

Inspector Notes

riverside stepboard issue. With warranty booklet, jack and tools. without spare tire. 1 key. with LTO plate. interior light issue.