


General Information

Date & Time: 14, Jun, 2025 12:29

Make	Isuzu	Model	Traviz
YOM	2020	Odo Meter Reading	50,052
Registration No.	NGB8183	Chassis No.	MHCPHR54DLJ501852
CC	2.5	Transmission	M/T
Fuel Type	Diesel	Type of Body	Van
Colour	White		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	71.2	73	70	70
2	Boot Lid	138.3	149	140	126
3	Roof	97.2	120	91	78/100
4	Left Front Fender	75.6	74	76	77
5	Left Front Door	105.4	119	88	109
6	Center Panel Left				
7	Left Rear Door				
8	Left Back Panel	106.2	106	96	117
9	Right Front Fender	76.5	81	74	75
10	Right Front Door	78.3	74	76	85
11	Center Panel Right				
12	Right Rear Door				
13	Right Back Panel	140.0	111	153	156

Overall Evaluation :

C

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : C	Exterior Evaluation : E
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Dashboard - Traces of Adhesive Tape - Yes / (R) Front Seat - Grime - Medium / Ceiling - Grime - Large / Rear Seat - Cut, Crack - Large / (L) Front Floor Mat - Cut, Crack - Small	Remarks (R) Side Gate - Scratch & Dent - Large / (L) Side Gate - Crack, Gap - Large / Rear Bumper, Lamps, Panels - Scratch & Dent - Large / Bonnet, Headlight - Scratch & Dent - Small / (L) Mirror - Scratch - Minimal / Roof - Dent - Large / (R) Front Door, Molding - Scratch - Medium / (L) Front Door, Molding - Scratch & Dent - Small / (L) Center Panel - Scratch - Small / Front Bumper, Grille, Lamps - Scratch - Medium / Front Windshield - Damaged - Large
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Reverse Camera - N/A - Yes

Inspector Notes
Crack Windshield. Without warranty booklet and tools. With jack and spare tire. 2 keys. with LTO plate