

General Information

Date & Time: 29, Oct, 2024 10:15

Make	Toyota	Model	Innova
YOM	2024	Mileage	11,269
Registration No.	NHM8700	Chassis No.	PA2JA8EM8R0136823
CC	2.8	Transmission	A/T
Fuel Type	Diesel	Type of Body	Wagon
Colour	Silver		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	123.6	125	129	117
2	Boot Lid	102.5	109	95	104
3	Roof	113.2	102	114	106/131
4	Left Front Fender	107.0	100	107	114
5	Left Front Door	114.6	115	120	109
6	Center Panel Left				
7	Left Rear Door	121.6	129	118	118
8	Left Back Panel	113.6	112	116	113
9	Right Front Fender	114.0	114	121	107
10	Right Front Door	114.3	116	118	109
11	Center Panel Right				
12	Right Rear Door	118.3	117	113	125
13	Right Back Panel	125.3	120	125	131

Overall Evaluation :

A

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

Interior Evaluation : A	Exterior Evaluation : C
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Defects not found	Remarks (R) Front Wheel, Cover - Scratch, Corrosion - Small / (R) Rear Wheel, Cover - Scratch, Corrosion - Small / (R) Step, In-panel, Side Spoiler - Scratch & Dent - Medium / (R) Rear Door, Molding - Scratch - Medium / (R) Rear Fender, Molding - Scratch - Minimal / (R) Front Fender, Molding - Scratch - Minimal / Front Bumper, Grille, Lamps - Scratch - Minimal / (L) Front Fender, Molding - Scratch - Small / (L) Front Door, Molding - Scratch - Small / (L) Rear Door, Molding - Scratch - Minimal / Rear Bumper, Lamps, Panels - Scratch - Minimal / Trunk Hood, Rear Gate - Dent - Small / Roof - Dent - Small / Bonnet, Headlight - Scratch - Minimal / (L) Front Wheel, Cover - Scratch, Corrosion - Small / (L) Rear Wheel, Cover - Scratch, Corrosion - Small / (R) Front Door, Molding - Dent - Minimal
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Defects not found

Inspector Notes