

General Information

Date & Time: 18, Jun, 2025 08:28

Make	Toyota	Model	Veloz
YOM	2024	Odo Meter Reading	19,254
Registration No.	CCD2626	Chassis No.	MHFAB18YXR3094024
CC	1.5	Transmission	CVT
Fuel Type	Gas	Type of Body	SUV
Colour	Black		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	101.6	107	96	102
2	Boot Lid	104.5	100	114	100
3	Roof	112.2	123	119	104/103
4	Left Front Fender	99.3	105	97	96
5	Left Front Door	113.0	107	111	121
6	Center Panel Left				
7	Left Rear Door	108.6	113	108	105
8	Left Back Panel	118.3	127	117	111
9	Right Front Fender	99.6	98	98	103
10	Right Front Door	114.6	118	114	112
11	Center Panel Right				
12	Right Rear Door	109.6	109	109	111
13	Right Back Panel	115.6	107	113	127

Overall Evaluation :

A

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : B	Exterior Evaluation : B
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Ceiling - Grime - Minimal / Rear Seat - Grime - Medium / (L) Front Trim - Grime - Small	Remarks (R) Mirror - Scratch - Minimal / (L) Front Door, Molding - Scratch - Minimal / (L) Rear Door, Molding - Scratch - Minimal / Front Bumper, Grille, Lamps - Scratch - Small / Rear Bumper, Lamps, Panels - Scratch - Small / (R) Rear Door, Molding - Scratch - Minimal / (R) Front Door, Molding - Scratch - Minimal / Roof - Scratch - Medium
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Spare Key - Issue - Unexist

Inspector Notes
With warranty booklet, spare tire, jack and tools. Without seatcover. With LTO plate.