

General Information

Date & Time: 29, Oct, 2024 14:28

Make	Toyota	Model	Avanza
YOM	2023	Mileage	25,415
Registration No.	DBG7141	Chassis No.	MHFAA1BY4N0011475
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	MPV
Colour	Red		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	108.0	110	101	113
2	Boot Lid	116.6	113	135	102
3	Roof	112.4	130	115	96/109
4	Left Front Fender	107.5	100	108	115
5	Left Front Door	118.0	113	115	126
6	Center Panel Left				
7	Left Rear Door	109.0	114	107	106
8	Left Back Panel	118.3	129	117	109
9	Right Front Fender	106.9	114	108	99
10	Right Front Door	111.6	113	113	109
11	Center Panel Right				
12	Right Rear Door	113.3	112	110	118
13	Right Back Panel	120.3	109	117	135

Overall Evaluation :

B

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

Interior Evaluation : B	Exterior Evaluation : C
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Sunvisor, Sunglass Holder - Crinkle - Medium / Console, Switches, Vents - Worn, Scratch, Cut, Crack - Small / Overall Interior - Smell - Yes	Remarks (R) Front Fender, Molding - Dent - Minimal / (R) Front Door, Molding - Scratch & Dent - Large / (R) Rear Fender, Molding - Dent - Minimal / (R) Rear Door, Molding - Scratch - Small / Rear Bumper, Lamps, Panels - Scratch & Dent - Small / (L) Front Door, Molding - Scratch - Medium / (L) Rear Fender, Molding - Scratch - Minimal / Front Bumper, Grille, Lamps - Scratch - Medium / Roof - Dent - Small
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Spare Key - Issue - Unexist

Inspector Notes
light scratches around the exterior. dirty aftermarket mattings.