

General Information

Date & Time: 05, Nov, 2024 17:31

Make	Toyota	Model	Raize
YOM	2023	Mileage	34,907
Registration No.	DBB6053	Chassis No.	MHKAA1BA2PJ081736
CC	1.0	Transmission	CVT
Fuel Type	Gas	Type of Body	SUV
Colour	Blue		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	161.6	157	178	150
2	Boot Lid	132.0	138	133	125
3	Roof	126.5	131	126	124/125
4	Left Front Fender	144.6	144	164	126
5	Left Front Door	142.3	140	147	140
6	Center Panel Left				
7	Left Rear Door	142.0	139	137	150
8	Left Back Panel	123.3	121	118	131
9	Right Front Fender	146.0	135	160	143
10	Right Front Door	150.3	144	162	145
11	Center Panel Right				
12	Right Rear Door	145.0	147	139	149
13	Right Back Panel	132.0	133	131	132

Overall Evaluation :

A

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

Interior Evaluation : A	Exterior Evaluation : B
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Dashboard - Traces of Adhesive Tape - Yes / Rear Seat - Grime - Small	Remarks (L) Mirror - Scratch - Small / Rear Bumper, Lamps, Panels - Dent - Small / Front Bumper, Grille, Lamps - Scratch - Medium
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Spare Key - Issue - Unexist

Inspector Notes

hairline scratches and swirl marks/ aftermarket floor mats/