


General Information

Date & Time: 23, Jun, 2025 15:02

Make	Toyota	Model	Yaris Cross
YOM	2023	Odo Meter Reading	23,608
Registration No.	CCA3445	Chassis No.	MHFAABAF1P0005791
CC	1.5	Transmission	CVT
Fuel Type	Gas	Type of Body	SUV
Colour	Red		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	112.3	118	105	114
2	Boot Lid	113.6	112	115	114
3	Roof	121.7	117	122	124/124
4	Left Front Fender	108.0	108	110	106
5	Left Front Door	107.3	100	110	112
6	Center Panel Left				
7	Left Rear Door	103.7	107	98	106
8	Left Back Panel	121.0	126	113	124
9	Right Front Fender	108.3	108	109	108
10	Right Front Door	107.3	113	108	101
11	Center Panel Right				
12	Right Rear Door	109.3	113	100	115
13	Right Back Panel	120.0	116	119	125

Overall Evaluation :

B

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : A	Exterior Evaluation : C
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks (R) Front Seat - Grime - Small / (L) Front Seat - Grime - Small	Remarks (L) Front Door, Molding - Scratch & Dent - Large / (L) Front Fender, Molding - Scratch & Dent - Medium / Front Bumper, Grille, Lamps - Scratch - Large / (R) Front Door, Molding - Dent - Minimal / (R) Rear Door, Molding - Scratch - Small / (R) Rear Fender, Molding - Scratch - Minimal / Rear Bumper, Lamps, Panels - Scratch - Small / (L) Rear Door, Molding - Scratch & Dent - Minimal / Trunk Hood, Rear Gate - Scratch - Minimal / Bonnet, Headlight - Scratch - Small / (L) Rear Fender, Molding - Scratch - Minimal
Frame Evaluation : A	Functional Evaluation : B
Remarks Defects not found	Remarks Battery - Weak - Yes

Inspector Notes
With LTO plate. no Tools and jack, Sparetire and warranty booklet. scratch headlight and tail light.